



AUSTRALIAN ASSOCIATION OF **LIVE STEAMERS**

AALS Web Site

www.aals.asn.au

Limited

ACN 107 882 404 - ABN 81 107 882 404

AUSTRALIAN MINIATURE BOILER SAFETY COMMITTEE

Chairman

Barry Potter
123 Gardiner Road
Orange, NSW 2800 Tel: (02) 6361 8694
Australia. E-mail: barrypotter@gotalk.net.au

Hon Secretary

Adrian Cox
18 Shoalhaven Street
Werribee, Vic. 3030 Tel: (03) 9741 5432
Australia. E-mail: acox@bigpond.net.au

Technical Representative

Bernie Dickinson -FIE (Aust) FIMES&T, CP Eng
63 Glengyle Terrace
Glendore, SA 5037 Tel: (08) 8297 5020
Australia Fax:(08) 8297 4919

AGENDA

MEETING to be held at the QUEENSLAND SOCIETY OF MODEL AND EXPERIMENTAL ENGINEERS INC grounds, Warner, Brisbane, on Friday 02nd April, 2010, at 7.30 pm.

1. Noel Eberhardt, the President of QSMEE will welcome all present and hand the meeting to the AMBSC Chairman, Barry Potter.
2. Barry Potter, the AMBSC Chairman, will open the meeting for business.
3. APOLOGIES: an attendance book will circulate.
4. MINUTES
5. CORRESPONDENCE
6. CHAIRMAN'S REPORT (circulated)

7. **Items for Discussion.**

5.1 Address by the AALS President, Roger Kershaw. He will speak about duties of the full AALS Board and the role of AMBSC (and ALSSC) in the Board.

5.2 Duplex Steel Boilers:

Where we stand on the proposal at this point – if the full Board is in a position to make a decision either for or against the proposal then the reasons for the decision will be given. If accepted there will then be a discussion on the implementation of the code. If rejected the Duplex committee may like to lodge an appeal.

5.3 Carbon Steel Boiler Code Revision:

A report on the revision as prepared by Andrew Mathews and reviewed by Eric Evans.

5.4 Copper Boiler Code:

A general discussion on possible changes to the code, such as cross stays etc.

5.5 Imported Boilers:

Consideration is being given to the importation of professionally made boilers provided that they are preceded by acceptable drawings and are suitably stamped and certified. Polly Models in the UK has been approached and has sent details of its copper boilers.

5.6 Working together:

Working relationships between boiler inspectors from the same club. Should there be a "Head Boiler Inspector" able to dictate to the others? Record keeping system? etc.

8. General Business.-----

Barry Potter, Chairman, AMBSC.